




# MIAMI-DADE FIRE RESCUE DEPARTMENT INSPECTION REPORT FIRE PREVENTION BUREAU

9300 NW 41ST STREET, DORAL, FLORIDA 33178-2424  
(786) 331-4800



Permit Number: **04121-00094**

Inspected: **November 1, 2023**

**DADE COUNTY PUBLIC SCHOOLS - DCPS**  
1450 NE 2 AVE ROOM 602  
MIAMI, FL 33132

Permit Type: **Education**  
Permit Use: **K-12 Public School**  
Permit Status: **Inspected / N.O.V. (30)**

Inspector: **RODRIGO JARAMILLO**  
Phone: **786-747-7560**  
Email: **rodrigo.jaramillo@miamidade.gov**

Inspected Address:

**DCPS DR CARLOS J FINLAY ELEMENTARY  
SCHOOL**  
851 - 851 SW 117 AVE  
MIAMI, FL 33174

**Violation(s)**

1.	Created	Comply By	Code
	11/1/2023	12/01/2023	FFPC 7th Edition, NFPA 1:

**Violation:** 50.5.2.1 Commercial Cooking. Semi-Annual Inspection. Fire Suppression System. Failure to have cooking hood fire suppression system inspected.

**Correction:** Have cooking hood fire suppression system inspected every 6 months by a licesned company, provide a current inspection and testing report; clear of any deficiencies or impairments.

**Comment:** CURRENT REPORT EXPIRED, PROVIDE HOOD SYSTEM SEMI-ANNUAL REPORT WITH NO DEFICIENCIES

2.	Created	Comply By	Code
	11/1/2023	12/01/2023	FFPC 7th Edition, NFPA 1:

**Violation:** 13.5.3.1 Backflow prevention devices shall be inspected, tested, and maintained in accordance with the requirements of NFPA 25, Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems

**Correction:** Inspect, test and maintain backflow prevention devices in accordance with the requirements of NFPA 25; provide report clear of deficiencies or impairments; provide documentation of correction of any deficiencies or impairments listed therein.

**Comment:** NO REPORT PRESENT PROVIDE BACKFLOW REPORT WITH NO DEFICIENCIES

3.	Created	Comply By	Code
	8/30/2021	09/29/2021	FFPC 7th Edition, NFPA 25:

<b>Violation Corrected</b> 11/01/2023
--

**Violation:** 7.1.4 Fire Hose. Inspection. Failure to maintain fire hose(s).

**Correction:** Have fire protection contractor perform annual inspection and maintenance on fire hoses.

**Comment:** HAVE FIRE PROTECTION COMPANY INSPECT AND SERVICE FIRE HOSE. YELLOW TAG



How did we do?  
We would like to hear about it.  
Scan the QR code to complete a survey.